

Part - 1

Performa For The Safety School Building
(To be filled by the Head of School / Institute)

SENITEL INTERNATIONAL SCHOOL RUN BY
BABA CHUHAN SINGH MEMO EDU TRUST

1. Name of School
2. Location
3. Plot Area
4. Plinth Area
5. Number of Storey
6. Year of Construction of building
7. Supervision of the qualified Engineer,
The following details may be given:
 - a) Name of the Engineer
 - b) Address
 - c) Set of Structure Drawing used in the construction if available
 - d) Name of the Architect
8. Whether the building has been constructed for the purpose of:
 - a) School
 - b) Residential purpose and converted for use as a school
9. Materials used for Roof:
 - a) R.C.C. slabs
 - b) R.S. Joists and Battens
 - c) Wooden Joists and Battens
10. Materials used for walls:
 - a) Mud Mortar
 - b) Cement Mortar
 - c) Plaster
 - (i) Lime Mortar
 - (ii) Cement Mortar
11. Flooring :
 - a) Conglomerate
 - b) Terrazzo
 - c) Brick Paving
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows

VILL - LADHRAN

8.23 ACR

70201-67 59FT

FIRST FLOOR, SECOND FLOOR, THIRD FLOOR

2019

SAL CONTRACTORS
CHANDIGARH

VIKRAM MALIK M.Arch, B.Arch
AIIAB A RM AIIA MCH

REQ. CA/20K/55257 CHANDIGARH

(Yes / No) YES

(Yes / No) NO

(Yes / No) YES

(Yes / No) NO

(Yes / No) NO

(Yes / No) NO

(Yes / No) YES

(Yes / No) YES

(Yes / No) NO

(Yes / No) NO

(Yes / No) YES

(Yes / No) NO

DRAWING ATTACHED

Signature with stamp of
The Head of the School / Institute

Principal
Sentinel International School
Lud-Chd Bypass, Bharthia Road Samrala (Ldh.)
Affiliated to C.B.S.E. New Delhi Vide No. 1631428

Part-II
(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 5/6/26 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.


The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 31/3/29 (indicate year up to which it can be used).

2026-29

Jaime (DE)


Sub Divisional Engineer

Sub. Divisional Engineer
Provi. Sub Division
PwD (B&R) Br. Samrala